TSCA NON-CONFIDENTIAL BUSINESS INFORMATION

DOCUMENT DESCRIPTION	SEMUK JOSTNOS TREMUSOS	DATE RECEIVED
CAIR	90-890000 238	16-13-89

ETHIMMENTS:



Form Approved OMB No. 2010-0019 Approval Expires 12-31-89

CONTAINS NO CBI

000657786\$ 90-89000238

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Comprehensive Assessment Information Rule

REPORTING FORM

hen completed, send this form to:

ocument Processing Center ffice of Toxic Substances, TS-790 .S. Environmental Protection Agency Ol M Street, SW ashington, DC 20460 ttention: CAIR Reporting Office

FOI /	4gei	1C V	use	Un	TA:			
Date	of	Rec	ceip	t:		 	 	

Document Control Number: _

Docket Number:

PA Form 7710-52

<u> </u>	A	SECTION 1 GENERAL MANUFACTURER, IMPORTER, AND PROCESSOR INFORMATION
PART	Α (GENERAL REPORTING INFORMATION
1.01	Th	is Comprehensive Assessment Information Rule (CAIR) Reporting Form has been
<u>CBI</u>	cor	npleted in response to the <u>Federal Register Notice of [1]2 [2]2</u>] [8]9] mo. day year
[_]	a.	If a Chemical Abstracts Service Number (CAS No.) is provided in the Federal
		Register, list the CAS No
	Ь.	If a chemical substance CAS No. is not provided in the <u>Federal Register</u> , list either (i) the chemical name, (ii) the mixture name, or (iii) the trade name of the chemical substance as provided in the <u>Federal Register</u> .
		(i) Chemical name as listed in the rule NA
		(ii) Name of mixture as listed in the rule
		(iii) Trade name as listed in the rule
	с.	If a chemical category is provided in the <u>Federal Register</u> , report the name of the category as listed in the rule, the chemical substance CAS No. you are reporting on which falls under the listed category, and the chemical name of the substance you are reporting on which falls under the listed category.
		Name of category as listed in the rule NA
		CAS No. of chemical substance [_]_]_]_]_]_]_[]-[_]
		Name of chemical substance
	7-11-1	
1.02	Ide	ntify your reporting status under CAIR by circling the appropriate response(s).
CBI	Man	ufacturer 1
	Imp	orter 2
		cessor(3)
		manufacturer reporting for customer who is a processor
		processor reporting for customer who is a processor
	lark	(X) this box if you attach a continuation sheet.

1.03 4 CBI	Does the substance you are reporting on have an "x/p" designation associated with it in the above-listed Federal Register Notice?						
	No .						
1.04 CBI	•	Do you manufacture, import, or process the listed substance and distribute it under a trade name(s) different than that listed in the Federal Register Notice? Circle the appropriate response.					
[_]		Yes					
		Check the appropriate box belov:					
		You have chosen to notify your customers of their reporting obligations Provide the trade name(s)					
		You have chosen to report for your customers You have submitted the trade name(s) to EPA one day after the effective date of the rule in the <u>Federal Register</u> Notice under which you are reporting.					
1.05 <u>CBI</u>	repor	ou buy a trade name product and are reporting because you were notified of your ting requirements by your trade name supplier, provide that trade name.					
[_]		e name					
	Yes .	in trade name product a mixture: Circle the appropriate response.					
	No						
1.06 <u>CBI</u>	sign	fication The person who is responsible for the completion of this form must the certification statement below: creby certify that, to the best of my knowledge and belief, all information					
	Rob	red on this form is complete and accurate. SIGNATURE DATE SIGNED					
	<u>C</u>	ter Manager (515) 270 - 2246 TITLE TELEPHONE NO.					
[<u></u>] M	ark (X) this box if you attach a continuation sheet.					

1:07 <u>CBI</u> [_]	Exemptions From Reporting If you have provided EPA or another Federal agency with the required information on a CAIR Reporting Form for the listed substance within the past 3 years, and this information is current, accurate, and complete for the time period specified in the rule, then sign the certification below. You are required to complete section 1 of this CAIR form and provide any information now required but not previously submitted. Provide a copy of any previous submissions along with your Section 1 submission.					
	information which I have not in	best of my knowledge and belief, and cluded in this CAIR Reporting Form and is current, accurate, and comp	n has been submitted			
	NA					
	NAME	SIGNATURE	DATE SIGNED			
		(<u> </u>	·. 			
	TITLE	TELEPHONE NO.	DATE OF PREVIOUS SUBMISSION			
1.08	CBI Certification If you have certify that the following state those confidentiality claims where the confidential ity claims where the con	ve asserted any CBI claims in this tements truthfully and accurately a	report you must			
<u>CBI</u>	and it will continue to take the been, reasonably ascertainable using legitimate means (other tangular a judicial or quasi-judicial prinformation is not publicly available to a substantial harm to	to protect the confidentiality of nese measures; the information is a by other persons (other than government of the second of t	not, and has not rnmeht bodies) by of special need in nsent; the of the information			
	NA					
	NAME	SIGNATURE -	DATE SIGNED			
	TITLE	TELEPHONE NO.				
	Mark (X) this box if you attach	a continuation sheet.				

PART	B CORPORATE DATA	
1.09	Facility Identification	
<u>CBI</u>	Name (Glololditielair) Clolminier Cloling Minier Cloling Time Cloling Minier Cloling Time Cloling Clolin	IIIei_i_
	(10131-1101-1101-1-1-1-1-1-1-1-1-1-1-1-1-	
	State State	[_]_]_]_
	Dun & Bradstreet Number [] _] _ [_] _] EPA ID Number [] _] _] _]	-(_1_1_1_1 -1_1_1_1+
	Employer ID Number	·[7]5]3]4]
	Other SIC Code	· (111
10	Company Headquarters Identification	
CBI	Name [T]h e] G o o d y e a r] T i r e & R u b Address [1]1 4 4 E a s t M a r k e t S t r Street	
	City (0 H (4 4 3 1 6 State	{ <u>0 0 0 1</u>
	Dun & Bradstreet Number	-(7) <u>9</u> 12141

1.11 Pare	ent Company Identification	1
CBI Name	e [T]hlel [G]olold [y]e a r] T]i r e & R	l <u>u b b e r </u>
[<u> </u>	ress $[\underline{1}]\underline{1}\underline{4}\underline{4}\underline{1}\underline{E}\underline{a}\underline{s}\underline{t}\underline{l}\underline{M}\underline{a}\underline{r}\underline{k}\underline{e}\underline{t}\underline{l}\underline{l}\underline{S}$	<u>t r e e t </u>
	·	$ \frac{1}{2} \frac{1}{6} -(0)\frac{1}{0}\frac{1}{0} \frac{1}{1} $
Dun	د Bradstreet Number	1
1.12 Techi	nical Contact	•
CBI Name	<u> </u>	
	· (CIEIDI HEITI IMAIDIA OITISI IIIIIIII)	111111
Addr	, and the second se	
Addi	Street	<u></u>
	DIEISITIMOITIDIEISITITITITITI	
	IJAI (510131 State	<u>3</u> <u>3</u> []]]]]]
Tele	ephone Number	17101-(三)三(平)五
1.13 This	s reporting year is from	
	Mo. Yea	er Ho. Year

1.14	Facility Acquired If you purchased this facility during the reporting year, provide the following information about the seller:
	NA .
<u>CBI</u>	Name of Seller [_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
[_]	Mailing Address []]]]]]]]]]]]]]]]]]
	(_1_1_1_1_1_1_1_1_1_1_1_1_1_1_1_1_1_1_1
	[_]_] [_]_]-[_]][_]]_]_ State
	Employer ID Number
	Date of Sale
	Contact Person []]]]]]]]]]]]]]]]]]
	Telephone Number
1.15	NA Facility Sold If you sold this facility during the reporting year, provide the following information about the buyer:
CBI	Name of Buyer []]]]]]]]]]]]]]]]]]
[_]	Mailing Address [_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	[_1_1_1_1_1_1_1_1_1_1_1_1_1_1_1_1_1_1_1
	[_]_] [_]_][_]_]_]_ State
	Employer ID Number
	Date of Purchase
	Contact Person []]]]]]]]]]]]]]]]]]
	Telephone Number
[_]	Mark (X) this box if you attach a continuation sheet.
	8

1.16	For each classification listed below, state the quantity of the listed was manufactured, imported, or processed at your facility during the re-	substance that
(<u></u>]	Classification	pantity (kg/yr)
	Manufactured	0
	Imported	. 0
	Processed (include quantity repackaged)	
	Of that quantity manufactured or imported, report that quantity:	
	In storage at the beginning of the reporting year	NA
	For on-site use or processing	
	For direct commercial distribution (including export)	
	In storage at the end of the reporting year	NA
	Of that quantity processed, report that quantity:	
	In storage at the beginning of the reporting year	721.
	Processed as a reactant (chemical producer)	0
	Processed as a formulation component (mixture producer)	C
	Processed as an article component (article producer)	25.2.2
	Repackaged (including export)	0
	In storage at the end of the reporting year	
		•
		;
		;
		1

Hark (X) this box if you attach a continuation sheet.

PART.	С	IDENTIFICATION	OF	MTYTIRES
	-	TODITALITON	O.L	HIALUKES

[_]

1.17 Mixture If the listed substance on which you are required to report is a or a component of a mixture, provide the following information for each component chemical. (If the mixture composition is variable, report an average perce each component chemical for all formulations.) CBI	
--	--

Component Name	Supplier Name	Average % Composition by Weight (specify precision,e.g., 45% ± 0.5%)
TDI Prepolymer	ARNCO	40 ± 5.0
Petroleum Hydrocarbon	ARNCO	55 ± 5.0
Toluene Diisocyanate	ARNCO	4.0 ⁺ 0.5
		Total 100%

[| Mark (X) this box if you attach a continuation sheet.

2.04	State the quantity of the listed substance that your facility manufa or processed during the 3 corporate fiscal years preceding the repor descending order.	ctured, imp	ported, in
CBI		1	
1_1	Year ending	. (<u>1</u>) <u>2</u>)	(<u>8</u>] <u>7</u>]
	Quantity manufactured	. b	kg
	Quantity imported		 kg
	Quantity processed		
	Year ending	[<u>1]2</u>]	[<u>8</u>] <u>6</u>]
	Quantity manufactured	0	. •kg
	Quantity imported		
	Quantity processed	176.6	kg
	Year ending	. [<u>1</u>] <u>2</u>]	[<u>8</u>]5] Year
	Quantity manufactured	c	kg
	Quantity imported	1	
	Quantity processed		
2.05 CBI	Specify the manner in which you manufactured the listed substance. appropriate process types.	Circle all	
	NA	; ;	
· ,	Continuous process	í 	1
	Semicontinuous process		2
	Batch process	: .4	3
		•	
		:	
		i 1	
1 1	Mark (X) this box if you attach a continuation sheet.	:	
	12	· · · · · · · · · · · · · · · · · · ·	

CBI '	appropriate process ty	which you processed th pes.	he listed substance.	Circle all
[_]				
	Continuous process	• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • • •	
	Semicontinuous process	•••••	• • • • • • • • • • • • • • • • • • • •	2
	Batch process	• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • • •	3
2.07 CBI	State your facility's r substance. (If you are question.)	name-plate capacity for a batch manufacture	or manufacturing or pr r or batch processor,	rocessing the listed do not answer this
[_]		NA		
	Manufacturing capacity		• • • • • • • • • • • • • • • • • • • •	kg/yr
	Processing capacity		• • • • • • • • • • • • • • • • • • • •	kg/yr
		•		
2.08 CBI	If you intend to increamanufactured, imported, year, estimate the increase volume.	OF Drocessed at any	time after your ourse	int corporate figari
[_]		Manufacturing Quantity (kg)	Importing Quantity (kg)	Processing Quantity (kg)
	Amount of increase	-		44,2
	Amount of decrease			3 1 1 2
				:
				:
				:
	•			
				i i
				;
				1
1	Mark (X) this box if yo	ou attach a continuati	ion sheet.	

•	2.09 For the three largest volume manufacturing or processing proclisted substance, specify the number of days you manufactured substance during the reporting year. Also specify the average day each process type was operated. (If only one or two oper list those.)	or processe e number of	d the listed
	CBI		
	[_]	Days/Year	Average Hours/Day
	Process Type #1 (The process type involving the largest quantity of the listed substance.)		
	Manufactured		
	Processed	80	_3
	Process Type #2 (The process type involving the 2nd largest quantity of the listed substance.)	•	•
	Manufactured		
	Processed	NA	
	Process Type #3 (The process type involving the 3rd largest quantity of the listed substance.)		
	Manufactured		
	Processed	NA	•
	2.10 State the maximum daily inventory and average monthly inventory substance that was stored on-site during the reporting year in the chemical. [] Maximum daily inventory Average monthly inventory	ry of the in the form	sted f a bulk kg
\			· .
	$[\underline{}]$ Mark (X) this box if you attach a continuation sheet.		
	14		

etc.). NA		Byproduct,	Concentration	Source product
CAS No.	Chemical Name	Coproduct or Impurity ¹	(%) (specify ± % precision)	product Impuri
		*		
llse the follo	ving codes to designat	te byproduct, copre	oduct. or impurit	V:
B = Byproduct C = Coproduct	ving codes to designat	te byproduct, copro	oduct, or impurit	y:
B = Byproduct	ving codes to designat	te byproduct, copro	oduct, or impurit	y :
B = Byproduct C = Coproduct	ving codes to designat	te byproduct, copro	oduct, or impurit	y:
B = Byproduct C = Coproduct	ving codes to designat	te byproduct, copro	oduct, or impurit	y :
B = Byproduct C = Coproduct	ving codes to designat	te byproduct, copro	oduct, or impurit	y:
B = Byproduct C = Coproduct	ving codes to designat	te byproduct, copro	oduct, or impurit	y:

<u>CBI</u>	imported, or processed the quantity of listed total volume of listed quantity of listed subslisted under column b., the instructions for fu	substance you use substance used duritance used captive	for each product type ing the reporting yearly on-site as a percent	reporting year. List as a percentage of th ar. Also list the
	a. Product Types ¹	b. % of Quantity Manufactured, Imported, or Processed	c. % of Quantity Used Captively	d.
	X	100	On-Site 100	Type of End-Users ² I, CM
				•
	<pre>1 Use the following code: A = Solvent B = Synthetic reactant C = Catalyst/Initiator, Sensitizer D = Inhibitor/Stabilize Antioxidant E = Analytical reagent F = Chelator/Coagulant, G = Cleanser/Detergent, H = Lubricant/Friction agent I = Surfactant/Emulsifi J = Flame retardant K = Coating/Binder/Adheen Use the following codes I = Industrial</pre>	Accelerator/ er/Scavenger/ Sequestrant Degreaser modifier/Antivear er esive and additives	L = Moldable/Castab M = Plasticizer N = Dye/Pigment/Col O = Photographic/Re and additives P = Electrodepositi Q = Fuel and fuel a R = Explosive chemi S = Fragrance/Flavo T = Pollution contr U = Functional flui V = Metal alloy and U = Rheological mod X = Other (specify) type of end-users:	on/Plating chemicals dditives cals and additives r chemicals ol chemicals ds and additives additives
	CM = Commercial	CS = Cons fi = Othe	umer r (specify)	
_1	Tark (X) this box if you	attach a continua	tion shoot	

}	explanation and an exam		(Ne	c.	ctions for further
	Product Types ¹	% of Quantity Manufactured, Imported, or Processed	_	% of Quantity Used Captively On-Site	Type of End-Users
	X	100	- -	100	I, CM
			- -		
	1 Use the following code A = Solvent B = Synthetic reactant C = Catalyst/Initiator Sensitizer D = Inhibitor/Stabiliz Antioxidant E = Analytical reagent F = Chelator/Coagulant G = Cleanser/Detergent H = Lubricant/Friction agent I = Surfactant/Emulsif J = Flame retardant K = Coating/Binder/Adh 2 Use the following code I = Industrial CM = Commercial	/Accelerator/ er/Scavenger/ /Sequestrant /Degreaser modifier/Antiwear ier esive and additives s to designate the CS = Cons	L : M : N : O : V : X : type	= Moldable/Castable = Plasticizer = Dye/Pigment/Colo = Photographic/Rep and additives = Electrodeposition = Fuel and fuel aco = Explosive chemical = Fragrance/Flavor = Pollution control = Functional fluid = Metal alloy and = Rheological mode = Other (specify) = of end-users:	cals and additives chemicals of chemicals and additives additives

	b.	c. Average % Composition of	d.
Product Type ¹	Final Product's Physical Form ²	Listed Substance in Final Product	Type of End-Users
<u> </u>	H	< 0.01	I, CM
,			:
			. '
	codes to designate pro		
agent I = Surfactant/Emu J = Flame retardan K = Coating/Binder	ator/Accelerator/ ilizer/Scavenger/ gent lant/Sequestrant gent/Degreaser tion modifier/Antiwear lsifier t /Adhesive and additive codes to designate the F2 = Cry F3 = Gra on F4 = Otl G = Ge	<pre>U = Functional fluid V = Metal alloy and W = Rheological mod es X = Other (specify) e final product's phys ystalline solid anules her solid</pre>	prant/Ink and addiprographic chemical ditives cals and additives chemicals of chemicals and additives additives affer Article-Flat pro
	codes to designate the	e type of end-users:	:
<pre>I = Industrial CM = Commercial</pre>	CS = Cor H = Otl	nsumer her (specify)	,

CBI	·liste	d substance to off-site customers.		or the						
[_]	Truck			1						
	Railc	ar		2						
	Barge, Vessel Pipeline									
	Plane 5									
	Other	(specify)	• • • • • • • • • • • • • • • • • • • •	6						

2.16 <u>CBI</u> []	or pr of en	mer Use Estimate the quantity of the listed substance epared by your customers during the reporting year for us d use listed (i-iv).	used by your o	customers category						
		ory of End Use	:							
	i.	Industrial Products	•							
		Chemical or mixture								
		Article	318.0	kg/yr						
	ii.	Commercial Products	•							
		Chemical or mixture		kg/yr						
		Article	35,3	kg/yr						
	iii.	Consumer Products	i !							
		Chemical or mixture		kg/yr						
		Article		kg/yr						
	iv.	<u>Other</u>	•							
		Distribution (excluding export)		kg/yı						
		Export	!	kg/yt						
		Quantity of substance consumed as reactant	,	kg/y						
		Unknown customer uses		kg/y:						
			;							
			, 1							

SECTION 3	PROCESSOR	RAW	MATERIAL	IDENTIFICATION

	TOOGGOOK MAN MATERIAL IDE	WITTICATION	:
PART	A GENERAL DATA		
3.01 <u>CBI</u>	Specify the quantity purchased and the average price for each major source of supply listed. Product trace The average price is the market value of the product substance.	oc are treet-1 -	
	Source of Supply	Quantity (kg)	Average Price (\$/kg)
	The listed substance was manufactured on-site.		•
	The listed substance was transferred from a different company site.	·	•
	The listed substance was purchased directly from a manufacturer or importer.		
	The listed substance was purchased from a distributor or repackager.		
	The listed substance was purchased from a mixture producer.	353.3	8.cc Ttl
3.02 CBI	Circle all applicable modes of transportation used to your facility.	deliver the lis	ted substance to
	Truck		
	Railcar	• • • • • • • • • • • • • • • • • • • •	2
	Barge, Vessel	• • • • • • • • • • • • • • • • • • • •	3
	Pipeline		4
	Plane		5
	Other (specify)	· · · · · · · · · · · · · · · · · · ·	6
	Mark (X) this box if you attach a continuation sheet.		

3.03 CBI	a.	Circle all applicable containers used to transport the listed substa facility.	nce	to your	
[_]		Bags		•••••	1
		Boxes		• • • • • • •	2
		Free standing tank cylinders			3
		Tank rail cars			4
		Hopper cars			5
		Tank trucks			6
		Hopper trucks			
		Drums			
		Pipeline		_	_
		Other (specify)			
t	٥.	If the listed substance is transported in pressurized tank cylinders cars, or tank trucks, state the pressure of the tanks.			•
		Tank cylinders		Hmm	g
		Tank rail cars			g
		Tank trucks			_
		BEST CONTRACTOR			

PART E	RAV MATERIAL IN THE F	ORH OF A MIXTURE		1
3.04 <u>CBI</u> [_]	or the mixture, the ham	e or its supplier(s) tion by weight of th	form of a mixture, list the or manufacturer(s), an est listed substance in the morting year.	imata af al
	Trade Name	Supplier or Manufacturer	Average % Composition by Weight (specify ± % precision)	Amount Processed _(kg/yr)
	Wingfil Part A	ARNCO	4.0 ± 0.5	8832
	·		-	
				•
			B K	: :
			Bless Copy Robert Alder	•
				· · · · · · · · · · · · · · · · · · ·
				•

3.05 CBI	State the quantity of the reporting year in the for the percent composition,	o II abamiaal am - 1	
		Quantity Used (kg/yr)	<pre>% Composition by Veight of Listed Sub- stance in Raw Material (specify ± % precision)</pre>
	Class I chemical	353.3	4.0 - 0.5
			-
	Class II chemical		
	Polymer		
			•
			• •
	•		
			:
			•
			Í

	SEC	CTION 4 PHYSICAL/CHEMIC	CAL PROPERTIES			
Gener	ral Instructions:			1		
	ou are reporting on a mix at are inappropriate to r			estions in Section		
notio	uestions 4.06-4.15, if yet that addresses the inmile in lieu of answering	formation requested, you	u may submit a copy or	l, MSDS, or other reasonable		
PART	A PHYSICAL/CHEMICAL DAT	ΓΑ SUMMARY				
4.01 <u>CBI</u>	substance as it is manu substance in the final	rity for the three major dfactured, imported, or product form for manufa or at the point you beg	processed. Measure that acturing activities, at	e purity of the the time you		
11		Manufacture	Import	Process		
	Technical grade #1	% purity	% purity NA-	mixture % purity		
	Technical grade #2	% purity	% purity	% purity		
	Technical grade #3	% purity	% purity	% purity		
	·	tity of listed substance		ed or processed.		
4.02	Submit your most recently updated Material Safety Data Sheet (MSDS) for the listed substance, and for every formulation containing the listed substance. If you posses an MSDS that you developed and an MSDS developed by a different source, submit your version. Indicate whether at least one MSDS has been submitted by circling the appropriate response.					
	Yes	• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • • •			
	No			• • • • • • • • • • • • •		
	Indicate whether the M	SDS was developed by yo	ur company or by a dif:	ferent source.		
	Your company			•••		
	Another source					

 $\{ \underline{\hspace{1cm}} \}$ Mark (X) this box if you attach a continuation sheet.



MATERIAL SAFETY DATA SHEET

REVISION DATE June 4 . 1986

BEST CONTRACTOR

I. GENERAL INFORMATION

PRODUCT NAME : WING-FIL COMPONENT "A"

CHEHICAL NAME : TDI Prepolymer plus Petroleum Hydrocarbon

CHEHICAL FAHILY : Isocyanate Prepolymer and Petroleum Hydrocarbon

: Proprietary DOT HAZARD CLASS : UN2078 (TDI)

HANUFACTURER ' : ARNCO, 5141 Firestone Place, South Gate, CA 90280-3570

Phone No: (213)567-1378

CHEHTREC Phone No: (800)424-9300 District of Columbia: (202)483-7616

II. INGREDIENTS

Components	- F		Vapor Press. mm Hg	ss. Dens. Limi		
TDI Prepolymer	ymer 0.02ppm 0.2mg/m3	Not Estab.	Not Estab.	0.02 @77°F.	6.0	Not Estab.
Petroleum Hydrocarbon	0.2mg/m ³ TWA-ACGIH	>300	>550	<1.0 @68°F.	<0.1	No Data Available

III. PHYSICAL DATA

BOILING POINT (°F) : 464 VAPOR PRESSURE (mm Hg) : SEE SECTION II VAPOR DENSITY (Air=1)

: SEE SECTION II SOLUBILITY IN WATER. \$: Insoluble. Reacts with water to liberate

CO2 gas.

APPEARANCE & ODOR : Dark brown liquid. Sharp pungent odor.

SPECIFIC GRAVITY $(H_2O=1)$: 1.01 VOLATILE BY VOLUME

: Negligible EVAPORATION RATE (Ether=1): Not Established

5141 FIRESTONE PLACE • P.O. BOX 1983 • SOUTH GATE, CALIFORNIA 90280 • (213) 567-1378 • (800) 762-7620 TWX 910-321-4155 --Page 1 of 4

FLASH POINT (°F)

FLAHHABLE LIHITS

EXTINGUISHING HEDIA

: 320
: Not Established
: Dry chemical, chemical foam, carbon dioxide

SPECIAL FIRE FIGHTING PROCEDURES: Fire fighters should wear full emergency equipment with self-contained pressure-demand breathing apparatus. Use water to cool fire-exposed containers. Eliminate all sources of ignition.

UNUSUAL FIRE & EXPLOSION HAZARDS: During a fire, toxic gases are genererated. Closed containers may explode from extreme heat or from water contamination. DO NOT reseal water-contaminated containers, as pressure buildup up may cause violent rupture of the container.

HEALTH HAZARD DATA

THRESHOLD LIHIT VALUE: 0.02 ppm; 0.2 mg/m³

SYMPTOMS OF EXPOSURE:

INHALATION: Hay cause dizziness and nausea. Irritation of the upper and lower respiratory tract. Some individuals may develop isocyante hypersensitization and must avoid further exposure to even low isocyanate levels. Inhalation of mists may present a cancer hazard. Sinusitis brochitis, asthma, and dmpaired wentilatory capacity can occur in some individuals.

INGESTION: Irritation and corrosive action in the mouth, stomach and digestive tract. Possibly liver toxicity. Aspiration into the lungs can cause chemical pneumonitis which can be fatal.

Liquid, vapors, or mist can cause sever irritation, redness, tearing, blurred vision and possibly irreversible damage to the eye.

SKIN: Irritation and allergic sensitivity may occur for some individuals, producing reddening, swelling or blistering, and skin sensitization, possibly resulting in dermatitis. This product contains petroleum oils similar to those catogarized by the International Agency for Research on Cancer (IARC) as causing skin cancer in mice after prolonged and repeated contact. Any potential hazard can be minimized by using recommended protective equipment to avoid skin contact and by washing thoroughly after handling.

CONTEMS

5141 FIRESTONE PLACE • SOUTH GATE CAUFORNIA 90280 • (213) 567-1378 • (213) 567-0587 • TWX 910-321-4156

Page 2 of 4

V. HEALTH HAZARD DATA (continued)

MEDICAL CONDITIONS AGGRAVATED BY EXPOSURE: Pre-existing unspecific bronchial hypersensitivity and, potentially, any allergies.

PRIMARY ROUTES OF ENTRY: Inhalation and skin contact.

EHERGENCY FIRST AID:

INHALATION: Remove victim to fresh air. If breathing is difficult, administer oxygen. If breathing has stopped, apply artificial respiration, and get medical attention immediately. NOTE TO PHYSICIAN: Treat symptomatically: bronchodilators; oxygen.

INGESTION: DO NOT INDUCE VOMITING. Aspiration can be fatal. Give a glass of milk or water, keep patient quiet and warm, and get prompt medical attention.

EYES: Flush immediately with water for at least 15 minutes, occasionally lifting the eyelid, and get prompt medical attention.

SKIN: Remove contaminated clothing and launder before reuse. Wash affected skin with soap and water. Consult a physician if swelling or reddening occurs.

VI. REACTIVITY DATA

STABILITY: Stable under normal, recommended storage conditions.

CONDITIONS TO AVOID: Open flame and storage temperatures above 120°F.

INCOMPATIBILITY: Haterials to avoid are water. alcohols, ammonia, amines, and alkalis. Contaminated containers should be left vented and be moved to a safe area for neutralization and proper disposal.

HAZARDOUS POLYHERIZATION: Hay occur.

CONDITIONS TO AVOID: Exposure to high temperature, or resealing of containers contaminated with materials listed under INCOMPATIBILITY (materials to avoid).

HAZARDOUS DECOMPOSITION PRODUCTS: Carbon monoxide and dioxide, nitrogen oxides, sulfur oxides, unidentified organ compounds, and traces of hydrogen cyanide (HCN).

82TICO

5141 FIRESTONE PLACE . SOUTH GATE, CAUFORNIA 90280 . (213) 567-1378 . (213) 567-0587 . TWX 910-321-4156

Page 3 of 4

VII. ENVIRONMENTAL PROTECTION PROCEDURES

SPILL RESPONSE: Evacuate and ventilate the area. Eliminate all sources of ignition. Respiratory protection must be worn during cleanup. Cover the spill with sawdust, vermiculite, or other absorbent material. Scoop and place in open container and remove to well ventilated area to be treated with a decontamination solution made up of 20% Tergitol THN-10 (Union Carbide) and 80% water; or 5% concentrated ammonia, 2% detergent, and 93% water. Leave the container open for 24-48 hours. Wash down the spill area with decontamination solution. For major spills call CHEMTREC: (800)

WASTE DISPOSAL METHOD Decontaminated waste must be disposed of in accordance with Federal, State, and local environmental control regulations. It sources Conservation and Recovery Act.

VIII. SPECIAL PROTECTION INFORMATION

EYE PROTECTION: Chemical workers goggles or full-face shield. Contact lenses should not be worn in or near work area.

RESPIRATORY PROTECTION: MSHA/NIOSH approved positive-pressure air-supplied respirator with full-face shield. Organic vapor filters are not effective against TDI vapor. The vapor pressure of TDI is such that at normal temperatures, vapor concentration in the air will exceed the TLV of 0.02 ppm.

SKIN PROTECTION: Impervious, chemical resistant (natural rubber) gloves, arm covers, aprons or coveralls, boots and caps.

VENTILATION RECOMMENDED: General mechanical ventilation and local exhaust. to maintain vapor concentration below the TLV.

OTHER PROTECTION: Safety showers and eye wash stations must be easily accessible. Provide a dry nitrogen blanket in bulk storage tanks.

IX. SPECIAL PRECAUTIONS

HYGIENIC PRACTICES IN HANDLING & STORAGE: Store below 100°F, preferably below 90°F, in tightly-closed containers to prevent atmospheric moisture contamination. DO NOT reseal if contamination is suspected. DO NOT store near open flame or high heat.

Wear protective equipment to prevent eye and skin contact. DO NOT breath vapors. Wash hands before eating or smoking.

Since emptied containers retain product residues (vapor or liquid), all hazard precautions given in this HSDS must be observed. For proper container disposal, fill with water and allow to stand <u>unsealed</u> for at least 48 hours then dospose of in accordance with Federal, State and local environmental control regulations.

THE INFORMATION IN THIS HSDS IS FURNISHED WITHOUT WARRANTY, EXPRESSED OR IMPLIED, EXCEPT THAT IT IS ACCURATE TO THE BEST KNOWLEDGE OF ARNCO. THE DATA ON THIS MSDS RELATES ONLY TO THE SPECIFIC MATERIAL DESIGNATED HEREIN. ARNCO ASSUMES NO LEGAL RESPONSIBILITY FOR USE OR RELIANCE UPON THIS DATA.

SATINGO

5141 FIRESTONE PLACE • SOUTH GATE CAUFORNIA 90280 • (213) 557-1378 • (213) 557-0587 • TWX 910-321-4155

Page 4 of 4

	>				:	
4.03	Submit a copy or reasonable facs that is provided to your custome formulation containing the liste been submitted by circling the a	rs/users read substance	garding the Indicate	listed subs	stance or any	ŕ
	Yes	• • • • • • • • • •	• • • • • • • • • • •			1
	No					(2
4.04 <u>CBI</u> [_]	For each activity that uses the corresponding to each physical s listed. Physical states for imp the time you import or begin to manufacturing, storage, disposal final state of the product.	tate of the orting and process the	listed subsprocessing a listed subs	stance durin activities a stance. Phy	ng the activit are determined ysical states	y at for
			Phy:	sical State	Liquified	
	Activity	Solid	Slurry	Liquid	Gas	Gas
	Manufacture	1	2	3	4	5
	Import	1	2	3	4	5
	Process	1	2	(3)	4	5
	Store	1	2	3	4	5
	Dispose	1	2	3	4	5
	Transport	1	2	3	4	5
	•				; ; ;	
					i i	
					:	

Mark (X) this box if you attach a continuation sheet.

_	
4.05	Particle Size If the listed substance exists in particulate form during any of the following activities, indicate for each applicable physical state the size and the percentage distribution of the listed substance by activity. Do not include particles >10 microns in diameter. Measure the physical state and particle sizes for importing and processing activities.
<u>CBI</u>	importing and processing activities at the time you import or begin to process the listed substance. Measure the physical state and particle sizes for manufacturing storage, disposal and transport activities using the final state of the product.

Physical State		Manufacture	T	_	_	1	
		Manufacture	Import	Process	Store	Dispose	Transport
Dust	<1 micron			NA		:	
	1 to <5 microns			NA		;	
	5 to <10 microns			NA			
						ı	•
Povder	<pre><1 micron</pre>	-		NA			
	1 to <5 microns			NA			
	5 to <10 microns		***************************************	NA			
Fiber	<l micron<="" td=""><td></td><td></td><td>NA</td><td></td><td></td><td></td></l>			NA			
	1 to <5 microns			NA .			
	5 to <10 microns			NA			
Aerosol	<1 micron			NA		-	
	1 to <5 microns			NA			
	5 to <10 microns		-	NA			

	<u> </u>	
,,	Mark (V) state to the	
· — '	Mark (X) this box if you attach a continuation sheet.	
	continuation sheet.	

SECTION	5	ENVIRONMENTAL.	CATE
SECTION		ENVIRUNTENIAL	PAIL

l :	Indicate the rate constants for the following transformation processes						
ŧ	a.	Photolysis:					
		Absorption spectrum coefficient (peak)	(1/M cm)	at	nm .		
		Reaction quantum yield, 6		at	nm		
		Direct photolysis rate constant, k_p , at	1/hr		latitud		
ł	b.	Oxidation constants at 25°C:		-			
		For ¹ 0 ₂ (singlet oxygen), k _{ox}			1/M		
		For RO, (peroxy radical), k_{ox}		•			
<	c.	Five-day biochemical oxygen demand, BOD ₅					
c	d.	Biotransformation rate constant:		i !			
		For bacterial transformation in water, $k_b \dots$,	1/hr		
		Specify culture		1	 		
€	е.	Hydrolysis rate constants:					
		For base-promoted process, k _B			1/M		
		For acid-promoted process, k,			1/M		
		For neutral process, $k_{_{\rm R}}$			1/hr		
f	f.	Chemical reduction rate (specify conditions)_		1			
8	ζ.	Other (such as spontaneous degradation)		i			
				•			

[] Mark (X) this box if you attach a continuation sheet.

5.02	a.	. Specify the half-life of the listed substance in the following media.					
				NA-Mixture			
		<u>Media</u>		Half-life (speci	y un	its)	
		Groundwater					
		Atmosphere		DED CUPY A			
		Surface water		SOFY A	VARI	A a	
		Soil			The state of the s	TULE	
	b.	Identify the listed s life greater than 24	ubstance's known t hours.	ransformation products	that	t have a half,-	
		CAS No.	<u>Name</u>	Half-life (specify units)		Media	
					in		
					in _		
		<u></u>			in †		
					in j		
				NA-Mixture			
5.03		cify the octanol-vater				at 25°0	
	Met	hod of calculation or o	determination		<u>-</u>		
5.04	Sno.	oifu the sail		NA-Mixture	<u> </u> 		
J.04		cify the soil-vater parts of type				at 25°0	
	501	1 (ype	••••••		:	······································	
5.05	Spe	cify the organic carbo	n-water partition	NA-Mixture			
		fficient, K				at 25°0	
5.06	Spe	cify the Henry's Lav Co	onstant, H	NA-Mixture		atm-m³/mole	
					:		

	type of test used in deriving	i	,
Bioconcentration Factor	NA-Mixture Species	Tes	<u>t </u>
		:	****
		:	
 		<u>_</u>	
¹ Use the following codes to	designate the type of test:		
F = Flowthrough		:	
S = Static	•	· · · · · · · · · · · · · · · · · · ·	
		:	
		i :	
		:	
		,	
		•	
		BEST COPY	AVAILABI
		<i>,</i>	
		į	
		:	

CBI	for each market listed below, state the listed substance sold or transfer	he quantity sold and the	e total sales value of
(<u> </u>)	Market Retail sales	Quantity Sold or Transferred (kg/yr)	Total Sales Value (\$/yr)
	Distribution Wholesalers Distribution Retailers Intra-company transfer		
\	Repackagers Mixture producers Article producers Other chemical manufacturers		
A	or processors Exporters Other (specify)		
(05			
6.05 <u>CBI</u>	Substitutes — List all known commerciation the listed substance and state the feasible substitute is one which is economy our current operation, and which reperformance in its end uses.	cost of each substitut	e. A commercially
***************************************	Substitute		Cost (\$/kg)
	No substitutes currently known		
1_1	Mark (X) this box if you attach a conti	nuation sheet.	
			·


General Instructions:

For questions 7.04-7.06, provide a separate response for each process block flow diagram provided in questions 7.01, 7.02, and 7.03. Identify the process type from which the

PART A MANUFACTURING AND PROCESSING PROCESS TYPE DESCRIPTION

7.01 In accordance with the instructions, provide a process block flow diagram showing the major (greatest volume) process type involving the listed substance.

Process type Batch - Polyurethane Polymerization



7A = TDI Prepolymer

7B = Amine Solution

7C = Metering Pump

7D = Isopropyl Alcohol Cleaning Solution

7E = Cleaning Solution Pump

7F = Components Mixing Head

7G = Tire Being Filled Through Valve Stem

7H = Clean-out Solution Drum


BEST COPY AVAILABLE

[|] Hark (X) this box if you attach a continuation sheet.

In accordance with the instructions, provide a process block flow diagram showing all process emission streams and emission points that contain the listed substance and which, if combined, would total at least 90 percent of all facility emissions if not treated before emission into the environment. If all such emissions are released from one process type, provide a process block flow diagram using the instructions for question 7.01. If all such emissions are released from more than one process type, provide a process block flow diagram showing each process type as a separate block.

CBI

Process type Batch - Polyurethane Polymerization



7A = TDI Prepolymer 7B = Amine Solution

7C = Metering Pump
7D = Isopropyl Alcohol Cleaning Solution

7E = Cleaning Solution Pump 7F = Components Mixing Head

7G = Tire Being Filled Through Valve Stem

7H = Clean-out Solution Drum



[]	Mark	(X)	this	box	i	you	attach	a	continuation	sheet.
-----	------	-----	------	-----	---	-----	--------	---	--------------	--------

ID Equi	ical pment pe	Operating Temperature Range (°C)	Operating Pressure Range	Vess
7A Drum		gc (0)	(mm Hg)	Compos
		Ambient	Atmospheric	Steel
7B Drum		Ambient	Atmospheric	Steel
7C Metering	Pump	Ambient	Atmospheric	Stain:
7D 5 Gallon	Can	Ambient	Atmospheric	Steel
7E Pump		Ambient	Atmospheric	Steel
7F Mixing He	ead	Ambient	Atmospheric	Stain
7G Tire		Ambient	Atmospheric	Vul. 1
7HDrum		Ambient	<u>Atmospheri</u> c	Steel
			:	der vide and de state of the st
			: :	
			:	
		96		
				ARIF
		90		

• •

•

, 7.05	process bloc	ck flow d	s stream identified in your iagram is provided for more e it separately for each pr	than one process type	iagram(s). If a e, photocopy this
CBI					
[_]	Process type		. Batch - Polyurethane	Polymerization	
	Process Stream ID Code		Process Stream Description	Physical State ¹	Stream Flow (kg/yr)
	7.1	TD	I Prepolymer	OL	8832
	7.3	TD	I Prepolymer	OL	8832
	7.6	Po	lymerizing Polyurethane	OL	17664.
			•		
		·			
		-			
	•				:
					1
			odes to designate the physi		dcess stream:
	SO = Gas (U SO = Solid SY = Sludge AL = Aqueou OL = Organi	or slur s liquid c liquid	le at ambient temperature a ible at ambient temperature ry uid (specify phases, e.g.,	and pressure)	e)
					!
				BEST COTT I	Vasiable !
<u> </u>	Mark (X) thi	s hov if	you attach a continuation	choos	:
,	(1)		you actach a continuation	sneet.	i
			4.6		•

,'7.06 CBI	It a proces this questi	e each process stream ides block flow diagram is pon and complete it separation for further explanation	orovided for mo atelv for each	re than one process type.	cess type, photocopy
[_]	Process typ		olyurethane Pol		
	a.	b.	c.	d.	e.
	Process Stream ID Code	Known Compounds ¹	Concen- trations ^{2,3} (% or ppm)	Other Expected Compounds	Estimated Concentrations (% or ppm)
	7.1	TDI Prepolymer	40 ± 5.0 (E) (W)	NA	NA
		Petroleum Hydrocarbon	55 = 5.0 (E) (W)	NA	NA
		Toluene Diisocyanate	4.0 ± 0.5 (E) (W)	NA	NA.
	7.3	TDI Prepolymer	40' ± 5.0 (E) (W)	NA NA	NA
		Petroleum Hydrocarbon	55 ± 5.0	NA	NA
		Toluene Diisocyanate	4.0 ± 0.5 (E) (W)	NA	NA
	7.6	Polyurethane	(원) - (유)	NA NA	NA NA
		Toluene Diisocyanate	(w) (a)	NA	· NA
		Amine	<u>(£) (w)</u>	NA	NA NA
7.06	continued b	elov			1
			6	Edu Gosti del	
					•
1_1	Hark (X) th	is box if you attach a co	ontinuation she	et.	

¹For each additive package introduced into a process stream, specify the compounds that are present in each additive package, and the concentration of each component. Assign an additive package number to each additive package and list this number in column b. (Refer to the instructions for further explanation and an example. Refer to the glossary for the definition of additive package.)

Additive Package Number		Components of Additive Package		Concentrations (% or ppm)
1				i
			-	:
				. '
2				•
				· · · · · · · · · · · · · · · · · · ·
3			_	
4				
			-	
5			-	
				:
			- 	
² Use the followi	ing codes to	designate how the cond	 centration va	s determined:
<pre>A = Analytical E = Engineering</pre>		alculation		;
³ Use the followi	ing codes to	designate how the cond	centration wa	s measured:
V = Volume				
V = Veight				1
Mark (X) this box	c if you atta	ch a continuation shee	2t.	i
Will the state of				

.01 <u>BI</u>	In accordance with the which describes the tre	instructions, provide a residatment process used for resid	dual treatment block flow diagraluals identified in question 7
_]	Process type	Batch - Polyurethane	Polymerization
		NA	:
			1
			•
			· · · ·
			:
		,	:
			:
			; ;
			i :
			!
			•
			BEST COPY AVAILABLE
		,	
			•
			:
			:

8.05 CBI	diagram process	n(s). If a r type, photo	residual treat copy this que	tment block f estion and co	in your residu low diagram is mplete it sepa r explanation :	provided for rately for ea	more than on ch process				
[_]	Process type Batch - Polyurethane Polymerization										
	a.	b.	C.	d.	e.	f.	g.				
	Stream ID Code	Type of Hazardous Vaste	Physical State of Residual ²	Known Compounds ³	Concentra- tions (% or ppm) ^{4,5,6}	Other Expected Compounds	Estimated Concen- trations (% or ppm)				
		,									
					BESTE	- 18/E					
						E					
											
8.05	continu	ed below				:					

¹Use the following codes to designate the type of hazardous waste:

I = Ignitable

C = Corrosive

R = Reactive

E = EP toxic

T = Toxic

H = Acutely hazardous

²Use the following codes to designate the physical state of the residual:

GC = Gas (condensible at ambient temperature and pressure)

GU = Gas (uncondensible at ambient temperature and pressure)

SO = Solid

SY = Sludge or slurry

AL = Aqueous liquid

OL = Organic liquid

IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene)

8.05 continued below



[] Mark (X) this box if you attach a continuation sheet.

8.05 (conti	nued)
--------	-------	-------

NA

For each additive package introduced into a process stream, specify the compounds that are present in each additive package, and the concentration of each component. Assign an additive package number to each additive package and list this number in column d. (Refer to the instructions for further explanation and an example. Refer to the glossary for the definition of additive package.)

	Additive Package Number	Components of Additive Package	Concentrations (% or ppm)
	1		
			;
	2	• •	
	3		
			<u> </u>
	4		
	· · · · · · · · · · · · · · · · · · ·	Per la companya de la companya della companya della companya de la companya della	GO PAMILLONG
	5		MILOS
			· · · · · · · · · · · · · · · · · · ·
	Use the following code	es to designate how the concentrati	ion vas determined:
	A = Analytical result		• •
	E = Engineering judgem	ent/calculation	
-			
8.05	continued belov		
	Mark (X) this box if yo	ou attach a continuation sheet.	

8.05	(cont	inued)
------	-------	--------

NA

 $^{5}\,\text{Use}$ the following codes to designate how the concentration was measured:

V = Volume

W = Weight

⁶Specify the analytical test methods used and their detection limits in the table below. Assign a code to each test method used and list those codes in column e.

Code	Method	Detection Limit (± ug/l)
<u>1</u>		
2	•	:
3		1
4		
5		
6		,

DOG COST ANALLAGIS

8.06	diagram process	(s). If a retype, photo	esidual trea copy this qu	d in your residual treatment block flow flow diagram is provided for more than one complete it separately for each process her explanation and an example.)							
CBI						•					
[_]	Process type Batch - Polyurethane Polymerization										
	a.	b.	C.	d.	e.	f. Costs for	g.				
	Stream ID Code	Waste Description Code	Management Method Code ²	Residual Quantities (kg/yr)	Management of Residual (%) On-Site Off-Site	Off-Site Management (per kg)	Changes in Management Methods				
						-					
	_	·			designate the waste	1					
[_]	Mark (X) this box i	f you attach	h a continua	tion sheet.						
****				58		<u> </u>					

WASTE DESCRIPTION CODES

These waste description codes were developed specifically for this survey to supplement the descriptions listed with the RCRA and other waste codes. (These waste description codes are not regulatory definitions.)

WASTE DESCRIPTION CODES FOR HAZARDOUS WASTE DESCRIBED BY A SINGLE RCRA F, K, P, OR U WASTE CODE

A01	Spent	solvent	(F001	-F005.	K086)
-----	-------	---------	-------	--------	-------

A02 Other organic liquid (F001-F005, K086)

A03 Still bottom (F001-F005, K086)

A04 Other organic studge (F001-F005, K086)

A05 Wastewater or aqueous mixture

A06 Contaminated soil or cleanup residue A07 Other F or K waste, exactly as described

A08 Concentrated off-spec or discarded

product

A09 Empty containers

"Exactly as described" means that the waste matches the description of the RCRA waste code

A10 Incinerator ash

A11 Solidified treatment residue

A12 Other treatment residue (specify in "Facility Notes")

A13 Other untreated waste (specify in "Facility Notes")

INORGANIC LIQUIDS—Waste that is primarily inorganic and highly fluid (e.g., aqueous), with low suspended inorganic solids and low organic content.

801 Aqueous waste with low solvents

B02 Aqueous waste with low other toxic organics

803 Spent acid with metals

B04 Spent acid without metals

B05 Acidic aqueous waste

B06 Caustic solution with metals but no cyanides

807 Caustic solution with metals and cyanides

808 Caustic solution with cyanides but no metals

B09 Spent caustic

810 Caustic aqueous waste

B11 Aqueous waste with reactive sulfides

B12 Aqueous waste with other reactives (e.g., explosives)

B13 Other aqueous waste with high dissolved solids

914 Other aqueous waste with low dissolved solids

B15 Scrubber water

B16 Leachate

B17 Waste liquid mercury

B18 Other inorganic liquid (specify in "Facility Notes")

INORGANIC SLUDGES—Waste that is primarily inorganic, with moderate-to-high water content and low organic content; pumpable.

819 Lime sludge without metals

820 Lime sludge with metals/metal hydroxide sludge

821 Wastewater treatment sludge with toxic organics

822 Other wastewater treatment sludge

823 Untreated plating sludge without cyanides

824 Untreated plating sludge with cyanides 825 Other sludge with cyanides

826 Sludge with reactive sulfides

827 Sludge with other reactives

828 Degreasing sludge with metal scale or filings

B29 Air pollution control device studge (e.g., fly ash, wet scrubber studge)

B30 Sediment or lagoon dragout contaminated with organics

831 Sediment or lagoon dragout contaminated with inorganics only

832 Onlling mud

833 Asbestos slurry or sludge

834 Chloride or other brine studge

B35 Other inorganic studge (specify in "Facility Notes")

INORGANIC SOLIDS—Waste that is primarily inorganic and solid, with low organic content and low-to-moderate water content; not pumpable.

836 Soil contaminated with organics

837 Soil contaminated with inorganics only 838 Ash, stag, or other residue from inciner-

ation of wastes 839 Other "dry" ash, slag, or thermal

Pasidue

"Dry" time or metal hydroxide solids chemically "fixed"

B41 "Dry" time or metal hydroxide solids not "fixed"

B42 Metal scale, filings, or scrap

843 Empty or crushed metal drums or containers

844 Battenes or battery parts, casings, cores 845 Spent solid filters or adsorbents

846 Asbestos solids and debns

B47 Metal-cyanide satts/chemicals

848 Reactive cyanide satis/chemicals

B49 Reactive sulfide salts/chemicals B50 Other reactive salts/chemicals

BS1 Other metal salts/chemicals

852 Other waste inorganic chemicals

BS3 Lab packs of old chemicals only

BS4 Lab pacts of debns only

855 Mixed lab packs 856 Other inormanic

 Other inorganic solids (specify in "Facility Notes")

INORGANIC GASES—Waste that is primarily inorganic with a low organic content and is a gas at atmospheric pressure.

B57 Inorganic gases

ORGANIC LIQUIDS—Waste that is primarily organic and is highly fluid, with low inorganic solids content and low-to-moderate water content.

858 Concentrated solvent-water solution 859 Halogenated (e.g., chlonnated) solvent

860 Nonhalogenated solvent

B61 Halogenated/nonhalogenated solvent mixture

B62 Oil-water emulsion or mixture

B63 Waste oil

B64 Concentrated aqueous solution of other organics

B65 Concentrated phenolics

B66 Organic paint, ink, lacquer, or varnish

B67 Adhesives or expoxies

868 Paint thinner or petroleum distillates

869 Reactive or polymerizable organic liquid

B70 Other organic liquid (specify in "Facility Notes")

ORGANIC SLUDGES—Waste that is primarily organic, with low-to-moderate inorganic solics content and water content; pumpable.

871 Still bottoms of halogeriated (e.g., chlori-

nated) solvents or other organic liquids 872 Still bottoms of nonhalogenated

solvents or other organic figuids

873 Oily sludge 874 Organic paint or ink sludge

B74 Organic paint or ink sludge B75 Reactive or polymerizable organics

876 Resins, tars, or tarry sludge

877 Biological treatment slugge

878 Sewage or other untreated biological sludge

879 Other organic studge (specify in "Facility Notes")

ORGANIC SOLIDS—Waste that is primarily organic and solid, with low-to-moderate inorganic content and water content; not pumpable.

880 Halogenated pesticide solid

881 Nonhalogenated pesticide solid

B82 Solid resins or polymenzed organics

883 Spent carbon

884 Reactive organic solid

B85 Empty fiber or plastic containers

B86 Lab packs of old chemicals only

857 Lab packs of deons only

888 Mixed tab packs 889 Other halogenati

189 Other halogenated organic solid

890 Other nonhalogenated organic solid

ORGANIC GASES—Waste that is primarily organic with low-to-moderate inorganic content and is a gas at atmospheric pressure.

891 Organic gases



EXHIBIT 8-2. (Refers to question 8.06(c))

MANAGEMENT METHODS

MANAGEMENT	r methods
M1 = Discharge to publicly owned	Possyame of columns and liquid and
vastevater treatment works	Recovery of solvents and liquid organics for reuse
M2 = Discharge to surface vater under	1SR Fractionation
NPDES	2SR Batch still distillation
<pre>H3 = Discharge to off-site, privately</pre>	3SR Solvent extraction
ovned vastevater treatment works	4SR Thin-film evaporation
M4 = Scrubber: a) caustic; b) water;	SSR Filtration
c) other	6SR Phase separation
MS = Vent to: a) atmosphere; b) flare;	7SR Dessication
c) other (specify)	8SR Other solvent recovery
H6 = Other (specify)	
TREATHENT AND RECYCLING	Recovery of metals
riduritari and recicented	1MR Activated carbon (for metals
Incineration/thermal treatment	recovery) 2MR Electrodialysis (for metals
1I Liquid injection	2MR Electrodialysis (for metals recovery)
2I Rotary or rocking kiln	3MR Electrolytic metal recovery
3I Rotary kiln with a liquid injection	4MR Ion exchange (for metals recovery)
unit	5MR Reverse osmosis (for metals
4I Tvo stage	recovery)
5I Fixed hearth	6MR Solvent extraction (for metals
6I Multiple hearth	recovery)
7I Fluidized bed	7MR Ultrafiltration (for metals
8I Infrared	recovery)
9I Fume/vapor	8MR Other metals recovery
10I Pyrolytic destructor	
11I Other incineration/thermal	Vastevater Treatment
treatment	After each vastevater treatment type
Reuse as fuel	listed below (1VT - 66VT), specify
1RF Cement kiln	a) tank; or b) surface impoundment
2RF Aggregate kiln	(i.e., 63VTa)
3RF Asphalt kiln	Faugliantia
4RF Other kiln	Equalization 1VT Equalization
5RF Blast furnace	Twi Equalization
6RF Sulfur recovery furnace	Cyanide oxidation
7RF Smelting, melting, or refining	2VT Alkaline chlorination
furnace	3VT Ozone
8RF Coke oven	4VT Electrochemical
9RF Other industrial furnace	SWT Other cyanide oxidation
10RF Industrial boiler	i
llRF Utility boiler	General oxidation (including
12RF Process heater	disinfection)
13RF Other reuse as fuel unit	GUT Chlorination
5 X - X - X	7VT Ozonation
Puel Blending	8VT UV radiation
1FB Fuel blending	9VT Other general oxidation
Solidification	
	Chemical precipitation:
The second secon	10UT Lime
2S Pozzolanic processes 3S Asphaltic processes	11UT Sodium hydroxide
4S Thermoplastic techniques	12VT Soda ash 13VT Sulfide
5S Organic polymer techniques	
6S Jacketing (macro-encapsulation)	14VT Other chemical precipitation
75 Other solidification	Chromium reduction
	15VT Sodium bisulfite
	16VT Sulfur dioxide

EXHIBIT 8-2. (continued)

MANAGEMENT METHODS

17VT Ferrous sulfate 18VT Other chromium reduction

Complexed metals treatment (other than chemical precipitation by pH adjustment) 19VT Complexed metals treatment

Emulsion breaking 20VT Thermal 21VT Chemical 22VT Other emulsion breaking

Adsorption
23VT Carbon adsorption
24VT Ion exchange
25VT Resin adsorption
26VT Other adsorption

Stripping 27VT Air stripping 28VT Steam stripping 29VT Other stripping

Evaporation
30VT Thermal
31VT Solar
32VT Vapor recompression
33VT Other evaporation

Filtration
34VT Diatomaceous earth
35VT Sand
36VT Multimedia
37VT Other filtration

Sludge devatering
38VT Gravity thickening
39VT Vacuum filtration
40VT Pressure filtration (belt, plate and frame, or leaf)
41VT Centrifuge
42VT Other sludge devatering

Air flotation
43VT Dissolved air flotation
44VT Partial aeration
45VT Air dispersion
46VT Other air flotation

Oil skimming 47UT Gravity separation 48VT Coalescing plate separation 49VT Other oil skimming

Other liquid phase separation : 50VT Decanting 51VT Other liquid phase separation

Biological treatment
52VT Activated sludge
53VT Fixed film-trickling filter
54VT Fixed film-rotating contactor
55VT Lagoon or basin, aerated
56VT Lagoon, facultative
57VT Anaerobic
58VT Other biological treatment

Other vastewater treatment
59VT Vet air oxidation
60VT Neutralization
61VT Nitrification
62VT Denitrification
63VT Flocculation and/or coagulation
64VT Settling (clarification)
65VT Reverse osmosis
66VT Other vastewater treatment

OTHER VASTE TREATMENT

1TR Other treatment 2TR Other recovery for reuse

ACCUMULATION

1A Containers 2A Tanks

STORAGE

1ST Container (i.e., barrel, drum)
2ST Tank
3ST Vaste pile
4ST Surface impoundment
5ST Other storage

DISPOSAL

1D Landfill
2D Land treatment

3D Surface impoundment (to be closed as a landfill)

4D Underground injection well

Chemical precipitation is a treatment operation whereby the pH of a vaste is adjusted to the range necessary for removal (precipitation) of contaminants. However, if the pH is adjusted solely to achieve a neutral pH, THE OPERATION SHOULD BE CONSIDERED NEUTRALIZATION (60VT).

8.22 CBI	(by capacity)	combustion chamber in inerators that	are used on	-site to burb (the residuals: id	argest entified in
	your process t	Combustion Chamber Temperature (Location of Temperature Monitor	Resid In Co	ence Time embustion (seconds)
	Incinerator 1	Primary Seco	ndary Pri	Mery Seconda	Primary Primary	Secondary
	2 3 Indicate	\if Office of Sol	id Waste sur			
	by circi	if Office of Sol	te response.	vey has been st	lomitted in iled	or response 1 2
8.23 CBI	are used on-si	ollowing table fo te to burn the re k flow diagram(s) NA	siduals iden	largest (by cap tified in your	pacity) incinera process block o	tors that r residual
[_]	Incinerator		Air Pollutio		Emissio	s of ns Data lable
	1					
	2					
	Indicate by circl	if Office of Sol ing the appropria	id Vaste sur te response.	 vey has been su	bmitted in lieu	of response
	Y e s	• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • • •		1
		• • • • • • • • • • • • • • • • • • • •				
		wing codes to des				
	E = Electrosta	(include type of satic precipitator ecify)				
[_]	Mark (X) this	box if you attach	a continuat	ion sheet.		

PART A EMPLOYMENT AND POTENTIAL EXPOSURE PROFILE

9.01	Mark (X) the appropriate column to indicate whether your company maintains records on
	the following data elements for hourly and salaried workers. Specify for each data
	element the year in which you began maintaining records and the number of years the
CBI	records for that data element are maintained. (Refer to the instructions for further
[-]	explanation and an example.)
l J	

Data Element	Hourly Workers	intained for Salaried Workers	Year in Which Data Collection Began	Number of Years Records Are Maintaine
Date of hire	X		1984	5
Age at hire	<u> </u>	×	1984	5
Work history of individual before employment at your facility	<u> </u>	. <u> </u>	1984	
Sex	<u>_x</u>		1984	5
Race			1984	5
Job titles			1984	5
Start date for each job title	<u>**</u>		1984	
End date for each job title	X		1984	5
Work area industrial hygiene monitoring data	-			· ·
Personal employee monitoring data	and the state of t			
Employee medical history		X	1984	5
Employee smoking history				1
Accident history	_X	X	1984	5
Retirement date	X	×	1984	S
Termination date		X	1984	5
Vital status of retirees				:
Cause of death data		***		

[_] Mark ((X) tł	his box	i f	you	attach a	continuation	sheet.
------------	--------	---------	-----	-----	----------	--------------	--------

9.02 . CBI	In accordance with th in which you engage.	e instructions, complete	the following ta	ble for ea	ach activity
[_]	a.	b.	c.	d.	e.
	•	Ç.		:	
	Activity	Process Category	Yearly Quantity (kg)	Total Workers	Total Worker-Hour
	Manufacture of the listed substance	Enclosed		•	
	Tisted sdostance	Controlled Release		: 	
		0pen			
	On-site use as	Enclosed	353.3		400
	reactant	Controlled Release		· i	•
		Open .			
	On-site use as	Enclosed			
	nonreactant	Controlled Release			
		0pen			
	On-site preparation	Enclosed			
	of products	Controlled Release			
		Open			
	•				
				•	
				;	
				•	
				:	


{__} Mark (X) this box if you attach a continuation sheet.

9.03	Provide a descriptive jencompasses workers who listed substance.	ob title for each labor category at your facil may potentially come in contact with or be ex	ity that posed to the
CBI			1
[_]			
	Labor Category	Descriptive Job Title	
	Α	Certified Fleet Specialist General Service	
	В	General Service	
	С	Retreader	•
	D		
	E		•
	F	•	
	G		
	Н		
	I		
	J		
			1
			•
			1
			:
			!
			; ;
			! !
()	Mark (X) this box if you	u attach a continuation sheet.	

9.04 In accordance with the instructions, provide your process block flow diagram(s) and indicate associated work areas.

CBI

| Process type Batch - Polyurethane Polymerization



7A = TDI Prepolymer

7B = Amine Solution

7C = Metering Pump

7D = Isopropyl Alcohol Cleaning Solution

7E = Cleaning Solution Pump

7F = Components Mixing Head

7G = Tire Being Filled Through Valve Stem

7H = Clean-out Solution Drum

Note: All above is considered one work area

9.05 CBI	Describe the various work area(s) shown in question 9.04 that encompass workers who may potentially come in contact with or be exposed to the listed substance. Add any additional areas not shown in the process block flow diagram in question 7.01 or 7.02. Photocopy this question and complete it separately for each process type.						
[_]	Process type	Batch - Polyurethane Polymerization					
	Work Area ID .	Description of Work Areas and Worker Activities Pumping TDI/Amine solutions to mixer, filling tires through value stem with polyurethane, and cleaning hosing with alcohol					
	2						
	3						
	4						
	5	•					
	6						
	7						
	8						
	9						
	10						
	Hark (X) this how if	BEST COPY AVAILABLE					

9.06 CBI	each labor come in con	e following tab category at you tact with or be e it separately	r facility tha exposed to th	t encompa e listed	sses worker substance.	s who may po Photocopy t	tentially		
[_]	Process type Batch - Polyurethane Polymerization								
	Work area .								
	Labor Category	Number of Workers Exposed	Mode of Exposu (e.g., dir skin conta	re ect	Physical State of Listed ubstance	Average Length of Exposure Per Day ²	Number of Days per Year Exposed		
	A	1	Air on	t	<u>వ</u> ం	A	- 		
	B	1	Air on	h	So	B	- <u>- 5</u> 0		
	<u> </u>	8	Air on	ly _	GC	B	5 0 .		
						THE STATE OF THE S			
						,			
					BES	T COPY AV			
						AV			
							E		
	GC = Gas (tempe GU = Gas (tempe inclu SO = Solic Use the fol A = 15 minu B = Greater exceedi C = Greater	llowing codes to fexposure: (condensible at erature and precure and precure and precudes fumes, vapilations codes to the feature and precure and precure for less to the feature and feature and feature and feature than one houring 2 hours	ambient ssure) at ambient ssure; ors, etc.) o designate av es, but not	SY = S AL = A OL = O IL = I (9 erage len	ludge or sl queous liqu rganic liqu mmiscible l specify pha 0% vater, l gth of expo eater than ceeding 4 h	urry id id iquid ises, e.g., 0% toluene) osure per day 2 hours, but nours 4 hours, but	: not		
[_]	Mark (X) thi	is box if you a	ttach a contin	uation sh	eet.	,			

.07 31	Weighted Average (egory represented in question 9.06 TWA) exposure levels and the 15-min stion and complete it separately for	nute peak exposure levels.
	Process type	Batch - Polyurethane Polymer	rization
'		••••••	1
	work area		15-Minute Peak Exposure Leve
	Labor Category	8-hour TVA Exposure Level (ppm, mg/m³, other-specify)	(ppm, mg/m³, other-specify)
	*	*	*
			!
		•	· · · · · · · · · · · · · · · · · · ·
		-	
			:
			;
	****		· · · · · · · · · · · · · · · · · · ·
¥			·
No	tests have been con	nducted	

9.08	If you monitor work	er exposur	e to the li	sted substa	nce, compl	ete the fo	llowing table.
CBI	No mo	nitor wo rk	ter exposure	available		,	
[_]		Work	Testing Frequency	Number of Samples	Who	,	Number of Years Records
	Sample/Test	Area ID	(per year)	(per test)	Samples'	(Y/N)	Maintained
	Personal breathing zone		-		************************	·	
	General work area (air)	**************************************			· · · · · · · · · · · · · · · · · · ·	·	
	Vipe samples	*****		•			•
	Adhesive patches						
	Blood samples			***		:	
	Urine samples						
	Respiratory samples						
	Allergy tests					i	
	Other (specify)			BEST	Copy Al	AILABLE	;
	Other (specify)						
	Other (specify)		***************************************			:	
	¹ Use the following of A = Plant industrian B = Insurance carr C = OSHA consultan D = Other (specify	al hygieni ier t	lesignate vh			ng samples:	
	Mark (X) this box i						

l	Sample Type	ical Methodol	ogy		
	P	NA			
					The second second
				And the second s	
)	If you conduct persons specify the following	al and/or ambien information for	it air monitoring for each equipment type	the listed :	substance,
		Do not conduct			
	Equipment Type ¹	Detection Limit	² Manufacturer	Averaging Time (hr)	Model Numb
					<u> </u>
	¹ Use the following coo		personal air monito		
	A = Passive dosimeter		, p = = = = = = = = = = = = = = = = = =	rang squarime.	cy pest
	<pre>B = Detector tube C = Charcoal filtrati D = Other (specify)</pre>	ion tube with pu	mp		
	Use the following coo	des to designate	ambient air monitor	ing equipmen	t types:
	E = Stationary monitor F = Stationary monitor G = Stationary monitor H = Mobile monitoring I = Other (specify)	ors located with ors located at p	in facility lant boundary cify)		· ·
	² Use the following coo			its:	
	A = ppm B = Fibers/cubic cent C = Micrograms/cubic	timeter (f/çc)			
	01	· · · · ·			i

		o tests	condu	cted		Freque	ency
]	Test Description				(weekly,	monthly	, yearly, etc.)
		<u> </u>					
							1
							•
							1
							:
							i
							: :
							•
							•
			BAR	d E .	y ARAMA		•
			-0	T Gir	^*.		•
				133-	A War		
					A	312	
						~C	
		_					•

Describe the engineering co to the listed substance. P process type and work area.	hotocopy this o			
Process type	. Batch -	Polyurethane Poly	merization	
Work area			1	
Engineering Controls	Used (Y/N)	Year Installed	Upgraded (Y/N)	Year Upgraded
Ventilation:			ė.	
Local exhaust	·		****	
General dilution				
Other (specify)			; ;	
Vessel emission controls		-		
Mechanical loading or packaging equipment			· · · · · · · · · · · · · · · · · · ·	
Other (specify)				
	•	Rec.		
			O DANAPIE	
			ARI.	
*Not aware that any engineering	g controls are	needed	; ;	
			1	
			•	
			•	

 $[\underline{ }]$ Mark (X) this box if you attach a continuation sheet.

ī	Describe all equipment or process modifications you have prior to the reporting year that have resulted in a reduct the listed substance. For each equipment or process modified percentage reduction in exposure that resulted. Photocomplete it separately for each process type and work are	ction of worker exposure t ification described, state tocopy this question and
_	Process type Batch - Polyurethane Polymeriza	tion
	Work area	
	Equipment or Process Modification	Reduction in Worker Exposure Per Year (%)
	Squipment of frocess notification	Exposure fer feat (%)
		·
		:
		<u> </u>
	No Modifications	; ;
		1 1 1
		•
		. !
		· •
		•
	Control of the second of the s	· }
		GERNAN !
		:

9.14	in each work area i	al protective and safety equenter or elimina py this question and completer	te their exposure	to the listed
CBI				
[_]	Process type	Batch - Polyurethane	Polymerization	·
	Work area	•••••	• • • • • • • • • • • • • • • • • • • •	1
		Equipment Turns	Wear or Use	·
		Equipment Types Respirators	M (A\N)	
		Safety goggles/glasses	Y	
		Face shields	<u>Y</u>	
		Coveralls	<u> </u>	;
		Bib aprons	<u>N</u>	
		Chemical-resistant gloves	<u> </u>	
		Other (specify)		
				!
				:
				i !
		,		1
				:

] Process type	e Bat	ch - Polyuretha	ne Polymer	ization	
Work Area	Respirator Type NA	Average Usage	Fit Tested (Y/N)	Type of Fit Test	Frequency of Fit Tests (per year)
A = Daily B = Weekly C = Monthly D = Once a E = Other	y year (specify)	·	-		
QL = Quali: QT = Quant:		ignate the type	of fit tes	; t: .	

	E WORK PRACTICES				·
9.19 CBI	Describe all of the work peliminate worker exposure authorized workers, mark a monitoring practices, provuestion and complete it se	to the listed su reas with warnin ide worker train	bstance (e.g. g signs, insuring programs,	, restrict en re worker det etc.). Phot	trance only to ection and ocopy this
]	Process type	Batch - Polymre	ethane Polymer	rization	· •
	Work area				
	work area	• • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • • •		
	Area is not restri	icted			·
					·
		*			
					,
	leaks or spills of the lis	ted substance.	rnotocopy thi	s questron un	d complete it
	Process type Vork area	s type and work Batch - Polyuret	area. hane Polymeri: 1-2 Times	zation 1 3-4 Times	More Than 4
	Process type Work area Housekeeping Tasks	s type and work Batch - Polyuret	area. hane Polymeri:	zation 1	More Than 4
	Process type Work area Housekeeping Tasks Sveeping	s type and work Batch - Polyuret Less Than Once Per Day	area. hane Polymeri: 1-2 Times	zation 1 3-4 Times	More Than 4
	Process type Work area Housekeeping Tasks Sweeping Vacuuming	s type and work Batch - Polyuret Less Than Once Per Day X	area. hane Polymeri: 1-2 Times Per Day	1 3-4 Times Per Day	More Than 4 Times Per Da
	Process type Work area Housekeeping Tasks Sweeping Vacuuming Vacuuming Vater flushing of floors	s type and work Batch - Polyuret Less Than Once Per Day	area. hane Polymeri: 1-2 Times Per Day	1 3-4 Times Per Day	More Than 4 Times Per Da
	Process type Work area Housekeeping Tasks Sweeping Vacuuming	s type and work Batch - Polyuret Less Than Once Per Day X	area. hane Polymeri: 1-2 Times Per Day	zation 1 3-4 Times	More Than 4 Times Per Da

9\21	Do you have a written medical action plan for responding to routine or exposure to the listed substance:	emergency
	Routine exposure	\
	\Yes\\\\	
	Emergency exposure	2
	Yes \	1
	No	2
	If yes, where are copies of the plan maintained?	
\	Routine exposure:	
	Emergency exposure:	
9.22	Do you have a written leak and spill cleanup plan that addresses the l	isted
	substance? Circle the appropriate response. Yes	1
	(No)	2
	Yes No If yes, where are copies of the plan maintained?	
	If yes, where are copies of the plan maintained? Has this plan been coordinated with state or local government response	organizations?
	Circle the appropriate response.	. 0180
	Yes	
	No	2
9.23	Who is responsible for monitoring worker safety at your facility? Ciappropriate response.	rcle the
	Plant safety specialist	
	Insurance carrier	2
	OSHA consultant	
	Other (spedify)	
[_]	Mark (X) this box if you attach a continuation sheet.	

SECTION 10 ENVIRONMENTAL RELEASE

General Instructions:

Complete Part E (questions 10.23-10.35) for each non-routine release involving the listed substance that occurred during the reporting year. Report on all releases that are equal to or greater than the listed substance's reportable quantity value, RQ, unless the release is federally permitted as defined in 42 U.S.C. 9601, or is specifically excluded under the definition of release as defined in 40 CFR 302.3(22). Reportable quantities are codified in 40 CFR Part 302. If the listed substance is not a hazardous substance under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) and, thus, does not have an RQ, then report releases that exceed 2,270 kg. If such a substance however, is designated as a CERCLA hazardous substance, then report those releases that are equal to or greater than the RQ. The facility may have answered these questions or similar questions under the Agency's Accidental Release Information Program and may already have this information readily available. Assign a number to each release and use this number throughout this part to identify the release. Releases over more than a 24-hour period are not single releases, i.e., the release of a chemical substance equal to or greater than an RQ must be reported as a separate release for each 24-hour period the release exceeds the RQ.

For questions 10.25-10.35, answer the questions for each release identified in question 10.23. Photocopy these questions and complete them separately for each release.

PART A	GENERAL INFORMATION	
10.01 CBI	Where is your facility located? Circle all appropriate responses.	
[_]	Industrial area	
	Urban area	2
	Residential area	3
	Agricultural area	4
	Rural area	5
	Adjacent to a park or a recreational area	6
	Within 1 mile of a navigable waterway	· 7
	Vithin 1 mile of a school, university, hospital, or nursing home faci	lity 8
	Within 1 mile of a non-navigable vaterway	· ·
	Other (specify)	10
[] 1	fark (X) this box if you attach a continuation sheet.	!

10.02	Specify the exact location of your fa is located) in terms of latitude and (UTM) coordinates.	arada di diizvo.	.Sai Itansvett	oc nereader
	Latitude	NA	o .	,
	Longitude	NA _	0	
	UTM coordinates Zone	, Northing	, Ea	asting
0.03	If you monitor meteorological condition the following information.	ons in the vicinity	of your faci	ility, provid
	Average annual precipitation			inches/y
	Predominant wind direction			
		. \		
٥.٥٤	Indicate the depth to groundwater belo	ov your famility.		
•				_
		_		
0.05	Depth to groundwater For each on-site activity listed, independent of the state of the s	icate (Y/N/N4) all	routine relega	meters ases of the
<u>BI</u>	For each on-site activity listed, indilisted substance to the environment. Y, N, and NA.)	icate (Y/N/NA) all (Refer to the inst	ructions for onmental Relea	ases of the a definition
31	For each on-site activity listed, indilisted substance to the environment. Y, N, and NA.) On-Site Activity	icate (Y/N/NA) all (Refer to the inst	onmental Relea	ases of the a definition ase
<u> </u>	For each on-site activity listed, indilisted substance to the environment. Y, N, and NA.) On-Site Activity Manufacturing	icate (Y/N/NA) all (Refer to the inst	ructions for onmental Relea	ases of the a definition
31	For each on-site activity listed, indilisted substance to the environment. Y, N, and NA.) On-Site Activity Manufacturing Importing	icate (Y/N/NA) all (Refer to the inst	onmental Relea	ases of the a definition ase
<u> </u>	For each on-site activity listed, indilisted substance to the environment. Y, N, and NA.) On-Site Activity Manufacturing	icate (Y/N/NA) all (Refer to the inst	onmental Relea	ases of the a definition ase Land NA
<u> </u>	For each on-site activity listed, indilisted substance to the environment. Y, N, and NA.) On-Site Activity Manufacturing Importing	icate (Y/N/NA) all (Refer to the inst	onmental Relea Vater NA	ases of the a definition ase Land NA NA
<u> </u>	For each on-site activity listed, indilisted substance to the environment. Y, N, and NA.) On-Site Activity Manufacturing Importing Processing	icate (Y/N/NA) all (Refer to the inst Environment Air NA NA NA NA	onmental Relea Vater NA NA	ases of the a definition ase Land NA NA
<u>31</u>	For each on-site activity listed, indilisted substance to the environment. Y, N, and NA.) On-Site Activity Manufacturing Importing Processing Otherwise used Product or residual storage Disposal	icate (Y/N/NA) all (Refer to the inst Environ Air NA NA NA NA N NA NA NA NA NA NA NA NA N	onmental Relea Vater NA NA NA NA	ases of the a definition ase Land NA NA NA NA
0.05 BI]	For each on-site activity listed, indilisted substance to the environment. Y, N, and NA.) On-Site Activity Manufacturing Importing Processing Otherwise used Product or residual storage Disposal	icate (Y/N/NA) all (Refer to the inst Environ Air NA NA NA NA N NA NA NA NA NA NA NA NA N	nmental Relea Vater NA NA NA	ases of the a definition ase Land NA NA NA NA NA
<u>BI</u>	For each on-site activity listed, indilisted substance to the environment. Y, N, and NA.) On-Site Activity Manufacturing Importing Processing Otherwise used Product or residual storage Disposal	icate (Y/N/NA) all (Refer to the inst Environ Air NA NA NA NA N NA NA NA NA NA NA NA NA N	nmental Relea Vater NA NA N NA N N N N N N N N N	ases of the a definition ase Land NA NA NA NA NA NA NA NA NA N
<u>BI</u>	For each on-site activity listed, indilisted substance to the environment. Y, N, and NA.) On-Site Activity Manufacturing Importing Processing Otherwise used Product or residual storage Disposal	icate (Y/N/NA) all (Refer to the inst Environ Air NA NA NA NA N NA NA NA NA NA NA NA NA N	nmental Relea Vater NA NA N NA N N N N N N N N N	ases of the a definition ase Land NA NA NA NA NA NA NA NA NA N

10.06	Provide the following information for the lister of precision for each item. (Refer to the instran example.)	d substance and speructions for furthe	ecify the level er explanation and
CBI	an enamples,		
[_]			
-	Quantity discharged to the air	NA	kg/yr <u>+</u> %
	Quantity discharged in wastewaters	NA	kg/yr <u>+</u> %
	Quantity managed as other waste in on-site treatment, storage, or disposal units	NA	kg/yr <u>+</u> %
	Quantity managed as other waste in off-site treatment, storage, or disposal units	NA	kg/yr <u>+</u> %



[] Mark (X) this box if you attach a continuation shee

10.08 CBI	for each process stre process block or resid	technologies used to minimize release of am containing the listed substance as idendual treatment block flow diagram(s). Phoately for each process type.	ntified in your
[_]	Process type	Batch - Polyurethane Polymerization	
		NA - Essential a closed system	1
	Stream ID Code	Control Technology	Percent Efficiency
			•
			:
			<u> </u>
		OCOT COLON	AUGUADUE
			MANUE
			; :

 $[\underline{ }]$ Mark (X) this box if you attach a continuation sheet.

10.09	Point Source	Emissions Id	entify each emission point source contain am ID Code as identified in your process	hing the listed
CBI	residual trea	tment block flo	w diagram(s), and provide a description of	of each point
[]	source. Do no sources (e.g.	ot include raw : , equipment lea!	material and product storage vents, or focks). Photocopy this question and comple	ugitive emission te it senarately
	for each proce	ess type.	ar, and the queetion and compac	ce it separately
	Process type	Ba [*]	tch - Polyurethane Polymerization	
	Point Source ID Code			· •
	TD Code		Description of Emission Point NA	Source
			IVA	
				•
			•	· · ·
				· ·
				, !
				1
				•
				-
				· ·
			B Ha.	
			BLST CUST SAUSA	
			~ £.	LADLE
				,
				•

attach a continuation sheet.

Mark

3

this

box i

you

Point		Stack Inner	NA .	Emission		1 1	
Source ID Code	Stack Height(m)		Exhaust Temperature (°C)	Exit Velocity (m/sec)	Building <u>Height(m)</u> ¹	Building Vidth(m)	
			with the control of t				
		•	***************************************			<u> </u>	
						. /	
	The December of the Control of the C		•				_
						<u>;</u>	
						*	_
						· · · · · · · · · · · · · · · · · · ·	_
1 Height o	f attached	or adjacent	building				
		or adjacent					
		codes to des	ignate vent	type:	BEST TOWN		
H = Hori V = Vert					BEST GOT	V. L. C. S. S. L.	
						:	
						•	

	Photocopy this question and c	ource ID Code identified in question 10.0 omplete it separately for each emission p	ooint source
]	Point source ID code	NA	
	Size Range (microns)	Mass Fraction (% \pm %	precision)
	< 1		
	≥ 1 to < 10	;	
	≥ 10 to < 30		
	≥ 30 to < 50		
	≥ 50 to < 100	•	
	≥ 100 to < 500		
	≥ 500		
		Total = 10	0%
		:	
		; !	
		:	
		BEST CONTRACTOR	BLE
		:	
		:	
		i	

[] Mark (X) this box if you attach a continuation sheet.

•			
PART	С	FUGITIVE	EMISSIONS

10.13 <u>CBI</u>	Equipment Leaks Complete the following table by providing the number of equipment types listed which are exposed to the listed substance and which are in service according to the specified weight percent of the listed substance passing through the component. Do this for each process type identified in your process block or residual treatment block flow diagram(s). Do not include equipment types that are not exposed to the listed substance. If this is a batch or intermittently operated process, give an overall percentage of time per year that the process type is exposed to the listed substance. Photocopy this question and complete it separately for each process type.						
[]	Process type Bato	h - Polvure	thane Pol	l vmerizati	ion		
	Percentage of time per year type	that the li	sted sub	stance is	exposed	to this p	cocess %
		Number	of Compo	nents in : d Substan	Service b	. — V Weight I	Percent.
	Equipment Type	Less than 5%	•				Greater
	Pump seals ¹	Clian Ja	5-10%	11-25%	26-75%	<u>76-99%</u>	than 99%
	Packed	×				•	
	Mechanical	-		~			
	Double mechanical ²	<u>X</u>					
	Compressor seals		-				
	Flanges	<u> </u>		*************************************		- :	
	Valves	X					*****
	Gas ³			_			
		<u>X</u>		BEST !	(* (288.9- 2)		
	Liquid	X			GOPYA	VALLA	
	Pressure relief devices (Gas or vapor only)	X'					<u> </u>
	Sample connections					į	
	Gas	×					
	Liquid					<u> </u>	**
	Open-ended lines ⁵ (e.g., purge, vent)				***************************************		-
	Gas	¥				1	
	Liquid				•	;	
	¹ List the number of pump and compressors	compressor	seals, n	ather tha	an the nur	mber of pu	ımps or
10.13	continued on next page					1	
	fark (X) this box if you atta	ch a contin	uation sl	neet.			

10.13	(continued)							
	² If double mechanical seal greater than the pump stu will detect failure of the with a "B" and/or an "S",	h a sensor (S) that						
	³ Conditions existing in th							
	4Report all pressure relie control devices			equipped with				
	⁵ Lines closed during norma operations	l operation that wou	old be used during	maintenance				
10.14 CBI	Pressure Relief Devices with Controls Complete the following table for those pressure relief devices identified in 10.13 to indicate which pressure relief devices in service are controlled. If a pressure relief device is not controlled, enter "None" under column c.							
[_]	a. NA	b.	c.	d.				
	Number of Pressure Relief Devices	Percent Chemical in Vessel	Control Device	Estimated Control Efficiency ²				
			BEGT					
				· · · · · · · · · · · · · · · · · · ·				
	Refer to the table in question 10.13 and record the percent range given under the heading entitled "Number of Components in Service by Weight Percent of Listed Substance" (e.g., $<5\%$, $5-10\%$, $11-25\%$, etc.)							
	The EPA assigns a control efficiency of 100 percent for equipment leaks controlled with rupture discs under normal operating conditions. The EPA assigns a control efficiency of 98 percent for emissions routed to a flare under normal operating conditions							
[]	Mark (X) this box if you at	tach a continuation	sheet.					

10.15	Equipment Leak Detec place, complete the procedures. Photocotype.	following table re	garding tho:	se leak dete	ection and re	epair
CBI					·	
[_]	Process type	• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • • •	Batch - Po	olyurethane I	Polymerization
		Leak Detection				
	NA	Concentration (ppm or mg/m³) Measured at Inches	Detection	Frequency of Leak Detection	Repairs Initiated (days after	Repairs Completed (days after
	Equipment Type	from Source	Device		detection)	
	Pump seals Packed Mechanical Double mechanical Compressor seals Flanges Valves Gas Liquid Pressure relief devices (gas or vapor only)			- China		
	Sample connections			OF Call	,	
	Gas .					
	Liquid			· · · · · · · · · · · · · · · · · · ·		
	Open-ended lines					
	Gas					
	Liquid				:	
	1Use the following co POVA = Portable org; FPM = Fixed point mo O = Other (specify)	anic vapor analyze	r	evice:		
[]	Mark (X) this box if	you attach a conti	nuation she	et.		

Control

(%)

Basis

for

Estimate

120

10.23		If there were more		d and when the release attach a continuation	
NA	Release	Date Started	Time (am/pm)	Date Stopped	Time (am/pm)

NH	Release	Date Started	Time (am/pm)	Date Stopped	Time (am/pm)
	1			1	****
	2				
	3	,		1	
	4				
	5				************
	6		•		
0.24	Specify the we	ather conditions at the	ne time of each r	release.	
		d Speed Wind Direction	Humidity (%)	Temperature (°C)	Precipitation (Y/N)

varease	(KM/III)	Direction	<u>(%)</u>	(°C)	(Y/N)
1					
2					
3	`				
4					
5					
			\ <u> </u>		
6					
	`				

[__] Mark (X) this box if you attach a continuation sheet.